




1 : 200

1 : 200



C1



1 : 50

TIPOS DE ACERO